




Chelsio Unified Wire for Linux

Release Notes



This document and related products are distributed under licenses restricting their use, copying, distribution, and reverse-engineering.

No part of this document may be reproduced in any form or by any means without prior written permission by Chelsio Communications.

All third-party trademarks are copyright of their respective owners.

THIS DOCUMENTATION IS PROVIDED “AS IS” AND WITHOUT ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, WITHOUT LIMITATION, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

THE USE OF THE SOFTWARE AND ANY ASSOCIATED MATERIALS (COLLECTIVELY THE “SOFTWARE”) IS SUBJECT TO THE SOFTWARE LICENSE TERMS OF CHELSIO COMMUNICATIONS, INC.



Chelsio Communications (Headquarters)

735 N Pastoria Avenue,
Sunnyvale, CA 94085
U.S.A

www.chelsio.com

Tel: 408.962.3600
Fax: 408.962.3661

Chelsio (India) Private Limited

Subramanya Arcade, Floor 3, Tower B
No. 12, Bannerghatta Road,
Bangalore-560029
Karnataka,
India

Tel: +91-80-4039-6800

Sales

For all sales inquiries, send an email to sales@chelsio.com

Support

For all support related questions, send an email to support@chelsio.com

Copyright © 2026. Chelsio Communications. All Rights Reserved.

Chelsio ® is a registered trademark of Chelsio Communications.

All other marks and names mentioned herein may be trademarks of their respective companies.

Document History

Version	Revision Date
1.0.0	01/30/2026
1.0.1	03/02/2026
1.0.2	03/31/2026
1.0.3	04/15/2026
1.0.4	04/30/2026
1.0.5	05/27/2026
1.0.6	06/08/2026

TABLE OF CONTENTS

I. CHELSIO UNIFIED WIRE	5
1. Introduction	6
2. New Features	6
3. Firmware Changelog	6
4. OptionROM Changelog	7
5. Fixed Issues	7
5.1. Network (NIC/TOE)	7
5.2. NVMe-oF/TCP PDU Offload	7
5.3. Crypto Offload	7
6. Known Issues	8
6.1. Network (NIC/TOE)	8
6.2. iWARP	10
6.3. RoCEv2	10
6.4. NVMe-oF iWARP	11
6.5. NVMe-oF/TCP PDU Offload	11
6.6. iSCSI PDU Offload	11
6.7. SPDK (user space) NVMe/TCP PDU Offload	12
6.8. SPDK (user space) NVMe/TCP over Memfree TOE	12
6.9. SPDK (user space) iSCSI PDU Offload	13
6.10. SPDK (user space) iSCSI over Memfree TOE (Target)	13
6.11. Crypto Offload	13
6.12. UDP Offload	14
6.13. Unified Boot Option ROM	14
6.14. Performance	15
6.15. Traffic Management	15
6.16. Installer	15

I. Chelsio Unified Wire

1. Introduction

This document provides details on Chelsio Unified Wire for Linux Release v4.2.1.2.

2. New Features

- Port Forwarding Mode (Hardware Bypass Mode/Fail-to-Wire/LAN Bypass) has been added for this release.

3. Firmware Changelog

- Firmware has been updated from 2.1.22.0 to 2.1.23.0.
- Firmware regions size have been extended to accomodate more core.
- Bug #46605: Enabled extended compliance code 0xC as 100G (4x25G) for QSFP type modules.
- RoCE Changes:
 - Corrected signaled bit for replay cases
 - Added enum value for RoCE IPv4 in firmware for readability
- Bug #45880: Configured ARM Clock PLL values for 1.172GHz.
- Bug #45345: New mailbox command FW_ACL_VI_CMD is added for PF to control VF's rxmode settings.
- Bug #46508, #45911: Added support for legacy modules based on compliance code and cable tech.
- Bug #46461: RX amplitude was reduced for optics, additionally check was added to avoid for DAC.
- Bug #46642: Updated MPS out_th value according to the current configured eth link speed.
- Bug #46682: Disabled a non-critical, informational firmware interrupt to reduce unnecessary overhead.
- Bug #46522: Disabled access of cxcnic if it is not yet initialized. Additionally, removed 200G capability from spider configuration
- Bug #46571: Fixed an issue where CR8 modules were misidentified
- Bug #46626: Fixed an issue where CMIS modules with a flat memory model (such as Amphenol CR8) were misidentified. The system now verifies that a module supports a paged memory model before attempting to write to the Page Select Byte, preventing I2C write errors.
- Bug #46695: Fixed port forwarding support port2 and port3 in 4-port adapters
- Bug #45882: Increased ARM uboot max size
- Bug #46721: Added support for IPv6 port forwarding in FW wire mode
- Bug #46722: Delay chip reset by a few milliseconds to ensure the host driver receives the mailbox command response.

4. OptionROM Changelog

- No changes in this release.

Disclaimer: This initial release may contain corner-case and platform-specific issues.

5. Fixed Issues

This section lists the fixed issues in this release of Chelsio Unified Wire for Linux.

5.1. Network (NIC/TOE)

Issue ID	Description/Workaround
45807	Description: Unloading of Chelsio NIC driver (cxgb4) on S7250 adapters is not supported if intel_iommu/amd_iommu is enabled.
45545	Description: Harmless error messages are observed while running chdebug.
45928	Description: 10GTek 200G SR module getting detected as active DA.

5.2. NVMe-oF/TCP PDU Offload

Issue ID	Description/Workaround
46277	Description: Unable to connect to cnvmet_tcp target on 6.18 kernel.

5.3. Crypto Offload

Issue ID	Description/Workaround
46241	Description: Single port/Dual port Rx perf for inline ipsec does not reach line rate at MTU of 1500

6. Known Issues

This section lists the known issues in this release of Chelsio Unified Wire for Linux.

6.1. Network (NIC/TOE)

Issue ID	Description/Workaround
44910	Description: BG drops seen while running traffic with pause disabled.
45440	Description: Other ports fails to link up, when 1st brought up port has DCBX enabled.
45482	Description: Bidirectional traffic with DDP enabled is not supported.
45559	Description: An incorrect or garbage value is observed for <code>rx_frames_64</code> in the ethtool stats output.
45592	Description: <code>rx_fcs_errors</code> and <code>rx_jabber</code> errors seen during traffic intermittently.
45594	Description: Pause frames received on Port1 are incorrectly populated under Port0 stats.
45605	Description: 2x200G Tx bandwidth is not going beyond 329 Gbps.
45645	Description: Offload bonding does not transfer traffic from the active slave to the backup slave upon port down.
45676	Description: 1x400G MTU 1500 Rx bandwidth not going beyond 352 Gbps.
45692	Description: Lower MTU are not supported.
45697	Description: Adapter fails to establish link and devlog reports "hw register operation not completing".
45824	Description: Host machine hibernation is not supported.
45843	Description: TX dual port performance does not reach line rate with 1500 MTU
45845	Description: On S series of adapters TX performance does not reach line rate at particular MTU values
45866	Description: 100G,25G and 10G speeds are not supported with 200G module.
45889	Description: Filtering: Ethertype 0x88a8(QinQ) and 0x9100 (QinQ) filters are not honored if the rule is configured with IPv6 protocol type.
45918	Description: 4 port adapters do not come up at PCIe x16 link speed on AMD machine when placed in PCIe5.0 x16 slot.
45923	Description: Port speed of 1G not supported with the 10G/25G/50G modules.
45940	Description: "Attempt to update new Transceiver Module settings failed" is seen in dmesg when DAC cables are used
45948	Description: ethtool does not report all supported link modes.
46002	Description: Driver load on PCIe Gen 3 is not supported.

Issue ID	Description/Workaround
46034/46082	Description: "Device did not become ready for access, whoami = 0xffffffff" message or "can't ioremap BAR 0: [??? 0x00000000 flags 0x0]" error observed intermittently in dmesg while loading driver on AMD based machines.
46037	Description: Intermittent IO stall seen during traffic due to link quality
46047	<p>Description: Flashing of Init/VPD files gets stuck when a jumper is connected after the system stays idle for some time.</p> <p>Workaround:</p> <p>Run below script and reattempt flashing of init/VPD:</p> <pre>[root@host ~]# PCIE_BUS=<bus_id> [root@host ~]# setpci -s \$PCIE_BUS COMMAND [root@host ~]# setpci -s \$PCIE_BUS COMMAND=\$(printf "%x" \$((0x`setpci -s \$PCIE_BUS COMMAND` 0x2))) [root@host ~]# cxgbtool /sys/bus/pci/devices/<bus_id>/ reg 0x05720=0x0 [root@host ~]# setpci -s \$PCIE_BUS COMMAND</pre> <p>Example –</p> <pre>[root@host ~]# PCIE_BUS=c7:00.0 [root@host ~]# setpci -s \$PCIE_BUS COMMAND [root@host ~]# setpci -s \$PCIE_BUS COMMAND=\$(printf "%x" \$((0x`setpci -s \$PCIE_BUS COMMAND` 0x2))) [root@host ~]# cxgbtool /sys/bus/pci/devices/0000\:c7\:00.0/ reg 0x05720=0x0 [root@host ~]# setpci -s \$PCIE_BUS COMMAND</pre>
46078	Description: 400G speed with FS.com optics is not supported on S71400 link
46111	Description: [cxgbtool] Firmware flashing via cxgbtool blocks SSH access until completion.
46121	Description: S series of adapters print incorrect offload debug values
46127	Description: Network offload transmit traffic is not supported on 6.12.x kernel if kernel is compiled on RHEL 9.6 on AMD setup with iommu enabled.
46134	Description: Data corruption seen while running TOE traffic.
46246	<p>Description: One of the Adapter fails to initialise, when multiple T7 Adapters placed on the system.</p> <p>Workaround: Known HW issue with respect to farthest PCI slot. Based on the motherboard schematics (refer below link), slot 1 and 3 are the farthest slots from the corresponding CPU sockets. Slots 2 and 4 are the closest ones where we do not see the failure.</p> <p>Refer - https://www.pugetsystems.com/parts/Motherboard/Gigabyte-MZ73-LM0-Rev-2-0-15236/ https://download.gigabyte.com/FileList/DataSheet/MZ73-LM0_datasheet_v2.0.pdf?v=238f7cfa14aa26cc84d567005d1e7b39</p>
46257	Description: Data corruption seen while running TOE DDP traffic with IOMMU enabled.
46341	Description: Link flap is seen when 50G optics were connected using QSA modules.

Issue ID	Description/Workaround
46350	Description: PCIe generation/speed does not change when PCIe lane width is set to anything other than x16 after reboot.
46357	Description: 200G link fails to come up on port-1 intermittently on T7-Rev-C B2B with fiber.
46363	Description: SGE stuck observed intermittently when it is placed in a Gen-3 machine.

6.2. iWARP

Issue ID	Description/Workaround
46547	Description: netstat/ethtool RX counters do not increment while running rping/ipperf over IPv6.

6.3. RoCEv2

Issue ID	Description/Workaround
46057	Description: "rdma statistic show" type of stats not available for RoCEv2.
46109/46115	Description: Certain rdma tools terminate abruptly with multiple connections.
46112	Description: Intermittent ping failure seen with NVME-RDMA initiator with multiple targets.
46116	Description: Reconnects seen with NVME-RDMA target.
46135	Description: Reconnects seen with NVME-RDMA target and third-party adapter as initiator.
46229	Description: mbw tool error outs intermittently with "cq error status 19" with bidirectional read/write test or terminates abruptly.
46306	Description: RoCE on VLAN interface is not supported.
46327	Description: iozone fails and ping fails with NFSoRDMA as a client with multiple connections (nconnect).

6.4. NVMe-oF iWARP

Issue ID	Description/Workaround
43201	Description: IO errors seen while running iSCSI + iWARP + TOE traffic.
45183	Description: OpenMPI versions < 5.x are not supported.
45736	Description: A memory leak is observed sporadically.
45933	Description: Errors observed when iWARP and NVMe-RDMA target traffic are run together.
46020	Description: Only one queue is used during NVMe/RDMA Initiator traffic.
46077	Description: [MTU: 1500/9000]: Dual port NVMe iWARP target perf is not reaching line rate.

6.5. NVMe-oF/TCP PDU Offload

Issue ID	Description/Workaround
44963	Description: An intermittent kernel panic is observed during the unload of driver following the cessation of PDU NVMe/TCP traffic.
45399	Description: The 'enable_h2c_data_zcopy' option is not supported.
45743	Description: Connections hang during negative header/digest error tests.
45755	Description: ISO counter not supported for Initiator.
46435	Description: Softlockup is observed intermittently.

6.6. iSCSI PDU Offload

Issue ID	Description/Workaround
45519	Description: [T7 CXGBIT]: High Target and initiator CPU usage is seen with cxgbit when compared with cxgbit4.
46054	Description: iSCSI PDU Offload is not supported on linux kernel 6.18.x.

Issue ID	Description/Workaround
46070	Description: iSCSI PDU Offload target, dual port write numbers are not reaching line rate.
46110	Description: Multi-portal target discovery incorrectly assigns an invalid portal to one target, resulting in login connection timeouts.

6.7. SPDK (user space) NVMe/TCP PDU Offload

Issue ID	Description/Workaround
45702	Description: Reconnects observed intermittently with heavy stress.
45812	Description: Initiator reports "cstor_cm.c:2483: _cstor_sock_disconnect: tid 11120, invalid state: aborting (6)"with stress.
46114	Description: Error messages seen on nvme_tgt application.
46356	Description: SPDK version 26.01 is not supported. Only spdk version 24.05 is supported

6.8. SPDK (user space) NVMe/TCP over Memfree TOE

Issue ID	Description/Workaround
46162	Description: Warning messages are observed on initiator while running traffic
46258	Description: Debug messages are observed on initiator while connecting to the target.
46259/46268	Description: Harmless "Nvme reconnect" messages are observed while running traffic.

6.9. SPDK (user space) iSCSI PDU Offload

Issue ID	Description/Workaround
45894	Description: ping failures and I/O errors intermittently when traffic is run for longer duration.

6.10. SPDK (user space) iSCSI over Memfree TOE (Target)

Issue ID	Description/Workaround
46168	Description: Trivial "_scsi_lun_execute_mgmt_task: *NOTICE*: Bdev scsi reset on target reset" messages are observed while running iozone traffic
46163	Description: Warning messages observed during iscsi discovery.
46349	<p>Description: Ping failure observed with traffic on linux-6.18.16.</p> <p>Workaround: Enabled iommu as shown below, reboot the host and run traffic again:</p> <pre>[root@host~]# grubby --args "iommu=on intel_iommu=on" -- update-kernel /boot/vmlinuz-6.18.16 [root@host~]# reboot</pre>
46364	Description: Link toggle while running traffic is not supported.

6.11. Crypto Offload

Issue ID	Description/Workaround
45342	Description: ccm not supported in user-mode.
45344	Description: NULL encryption and AES-GMAC authentication not supported.
45372	Description: UDP receive tests over IPsec tunnels configured via ip xfrm results in drop counters increment.
45421	Description: IPsec tunnel creation on inactive interfaces not supported using ip xfrm.

Issue ID	Description/Workaround
45465	Description: GRO, TSO, and checksum counters not supported for ESP packets.
45467	Description: Connections errors seen with cxgb4i initiator.
46027	Description: Bandwidth impact observed due to ESP checksum-segmentation dependency.
46048	Description: Single port inline ipsec does not reach line rate with MTU value of 1500
46394	Description: Per-Port IPsec and TOE-TLS counters incorrectly increment across multiple ports.
45820	Description: Kernel panic is observed with wrk application traffic if openssl 3.5.4 or openssl 3.6.0 is used.
46274	Description: Traces observed during OpenSSL traffic followed by ping failure.

6.12 UDP Offload

Issue ID	Description/Workaround
45759	Description: UOTIDS stuck issue observed and connection loss occurred while running UDP_SO traffic in a loop without pacing rules.

6.13. Unified Boot Option ROM

Issue ID	Description/Workaround
45397	Description: PXE legacy mode is not supported
45802	Description: iSCSI is not supported.
45859	Description: ALT+C cannot be used to access configuration utility.

6.14. Performance

Issue ID	Description/Workaround
45852	Description: Transmit (TX) and Receive (RX) throughput is lower when using small I/O sizes.
45852/45957	Description: Improvement needed for iSCSI PDU Offload target single/dual port bidi numbers.
46029	Description: Read performance is less for lower IO sizes compared with write.

6.15. Traffic Management

Issue ID	Description/Workaround
45657	Description: Throughput drop observed with flow-based TM as the number of connections increases.

6.16. Installer

Issue ID	Description/Workaround
46160	<p>Description: cxgb4i (iSCSI PDU Offload Initiator driver) fails to compile on Rocky10.0 with imprecise kernel source</p> <p>Workaround: Compilation must be attempted with KSRC and KOBJ options with the exact kernel source version.</p> <p>Follow the steps below:</p> <ol style="list-style-type: none"> Download the exact Kernel source matching the kernel version: <pre>[root@host ~]# make KSRC=<path_to_kernel_source_directory>/ KOBJ=/lib/modules/<kernel_version>/build/</pre>
46420	Description: SPDK (user space) tool binaries (nvme_tgt and iscsi_tgt) do not get installed with the RPM package.